

Clean Shot - Usage Guide

The following guide describes Clean Shot's cleansing potential. With so many variables to consider including line size lengths and diameters, system age and service history, these ratios will vary. The most sensible practice is to introduce Clean Shot to the lines in 30-90 second bursts until the color of the solvent leaving the crimped end of the line is relatively clear. Remember to keep the Clean Shot cylinder in the upright position. Weigh your Clean Shot cylinder before and after use so you can determine the actual cleaning costs. Please follow the complete user guidelines printed on the side panel of the Clean Shot box.

1 pound - 2 - 4 ton system

2 pounds – up to 5 - 7 ton system

5 pounds – up to 20 ton system

10 pounds - up to 40 ton system

TECH₂TECH 

REFRIGERANT RELATED
DIAGNOSTIC SUPPORT

For additional technical support
call ICOR's toll free Tech-2-Tech
hotline at **(866) 433-8324**

